



Elma Schmidbauer GmbH · Postfach 280 · D-78202 Singen

Release Notes – Elmasolvex VA R016

Changes to the Elmasolvex VA software from version R015 to R016

New:

-

Bug fixes:

F1

An error was fixed that caused the machine not to drain the liquid after a power failure and subsequent restart.