



Elma Schmidbauer GmbH · Postfach 280 · D-78202 Singen

Release Notes – Elmasolvex VA R015

Changes to the Elmasolvex VA software from version R014 to R015

New:

-

Bug fixes:

1. Fixed an error that could cause an incorrect entry "Error 271" in the event list every time the machine was switched on via the main switch.